

Figure 12 Fiber Optic Conduits On A Concrete Culvert
That Passes Under I-15




Figure 13 Wall Support Details For The Fiber Optic
Conduits Of Figure 12




Figure 14 Surface Water Conditions Near The Toe Of The I-15S Retaining Crib Wall




Figure 15 Fiber Optic Conduits Under a Heavy Water Pipe, Both On A Highway Bridge